

Please submit a *Quality Control Report* if you notice issues with the wheelchairs or spare parts you receive.


Example

FWM WHEELCHAIR QUALITY PROBLEMS REPORT							
COUNTRY: Peru			ORGANIZATION: Camino de Vida				
GEN TYPE	SIZE (S, M, L, XL)	PO #	PART	ISSUE DESCRIPTION- Pictures Needed	ISSUE ID#	NAME & DATE	
1	2 3	s	072016	Cross Bar	Cross bar hole not punched thru	#1	Raul - Peru - 11/3/17
1	2 3	L	072016	Bolt	Broken bolt	#2	Bonnie - Peru - 11/3/17

Issue #1



Issue #2



If you notice issues with the wheelchairs or spare parts you receive, please submit a *Quality Control Report* by downloading the form, and emailing to Bonnie Gonzalez at bgonzalez@freewheelchairmission.org with Subject line: QC Report – [Country], e.g. “QC Report – Peru”.